Please do not remove this label until the software update is complete.

New Chamber Door

You have received the newest version of the chamber door.

Install the door using the instructions provided. The procedure is the same as with the current door.

The machine's software must be updated prior to use once the new door is installed.

Once installed immediately call:

RIS Technical Support @ 858-779-9148, Opt. 3
to update the software.

Please do not remove this label until the software update is complete.

