

The location of the “Top 10 Issues” platform has changed. Please bookmark the following URL for easy access – <http://training.retailinkjet.com/top10/>

Objective: This week’s issue will cover the following subject.

- 🔧 Home Position of Infusion Pump

Benefits:

- 🔧 Markings on the valve motors to help identify home position
- 🔧 Eliminate the guess work when installing a new infusion pump

We will be marking the home position of valve motor shafts by painting the **bottom half with an orange fluorescent paint marker**. The marking on the shaft will indicate that the motor drive motor is set at home position. This change will make easier for us and all the techs.



Contact Information For service related support, please call RIS @ 1-858-779-9148 Option 3