



Service Update InkCenter

Revised 05/24/2013 Ver A
Questions?
Contact:
whoeckh@retailinkjet.com

Objective: Provide information on what is new with the Ink Center

Contact Information For service related support, please call RIS @ 1-858-779-9148 Option 3

New Error Codes

- There are some new Vacuum error codes. Below you find the complete list of vacuum errors and their definition.
 - V001 Vacuum measured at separator < 5in/hg
 - V002 Vacuum measured at separator < 14.4in/hg
 - V003 Vacuum measured at prep station > 3 before opening vacuum valve
 - V004 Vacuum measured at separator < 14.4in/hg in 5 seconds
 - V005 Moderate chamber leak
 - V006 Severe chamber leak
 - V007 Prep vent valve not opening

- Waste Errors
 - W001 Waste Full Sensor reads "full" after running waste drain routine.

Video #40 (Individual Ink Tank Refill & Care Tips)

Check out the latest Video showing some nice details of ink jet technology and the newest cartridges now being filled in the InkCenter.

http://inkjet411.retailinkjet.com/?page_id=1991